

Toggle menu
Blue Gold Program Wiki

Navigation

- [Main page](#)
- [Recent changes](#)
- [Random page](#)
- [Help about MediaWiki](#)

Tools

- [What links here](#)
- [Related changes](#)
- [Special pages](#)
- [Permanent link](#)
- [Page information](#)

Personal tools

- [Log in](#)

personal-extra

Toggle search
Search

Random page

Views

- [View](#)
- [View source](#)
- [History](#)
- [PDF Export](#)

Actions

File:P29 BGP erosion presentation.pdf


From Blue Gold Program Wiki

The printable version is no longer supported and may have rendering errors. Please update your browser bookmarks and please use the default browser print function instead.

- [File](#)
- [File history](#)
- [File usage](#)




1




2

Go to page Go!



3



4



[next page →](#)

1

Size of this JPG preview of this PDF file: [800 × 566 pixels](#). Other resolution: [320 × 226 pixels](#).

[Original file](#) (1,754 × 1,240 pixels, file size: 3.49 MB, MIME type: application/pdf, 9 pages)

Summary[edit | edit source]

Study of riverbank erosion (revised edition incorporating EM comments)

the removal of materials in the river bank by water flowing in the river channel; also termed bank scour. In coastal polders, riverbank erosion - if unchecked - can result in breaches to polder embankments - where they are aligned close to rivers - and consequent loss of human and animal life as well as damage to farmland, crops, housing, and other infrastructure.

File history

Click on a date/time to view the file as it appeared at that time.

Date/Time	Thumbnail	Dimensions	User	Comment
current 04:18, 10 March 2021		1,754 × 1,240, 9 pages (3.49 MB)	Bigblue (talk contribs)	Updated file

[05:59, 28 June 2020](#)



1,239 × 1,754, 6
pages (654 KB)

[Bigblue](#) ([talk](#)
[contribs](#))

Study of riverbank
erosion (revised
edition
incorporating EM
comments)

You cannot overwrite this file.

File usage

The following page uses this file:

- [File:P29 BGP erosion presentation 23apr 17.pdf](#) (file redirect)

Retrieved from

"https://www.bluegoldwiki.com/index.php?title=File:P29_BGP_erosion_presentation.pdf&oldid=4443"

Namespaces

- [File](#)
- [Discussion](#)

Variants

[Categories:](#)

- [P29](#)
- [IWM](#)
- [Report](#)
- [Documents in English](#)
- [Study](#)
- [Erosion](#)
- [BGIF](#)

This page was last edited on 10 March 2021, at 04:18.

Blue Gold Program Wiki

The wiki version of the Lessons Learnt Report of the Blue Gold program, documents the experiences of a technical assistance (TA) team working in a development project implemented by the Bangladesh Water Development Board (BWDB) and the Department of Agricultural Extension (DAE) over an eight+ year period from March 2013 to December 2021. The wiki lessons learnt report (LLR) is intended to complement the BWDB and DAE project completion reports (PCRs), with the aim of recording lessons learnt for use in the design and implementation of future interventions in the coastal zone.

- [Privacy policy](#)

- [About Blue Gold Program Wiki](#)
- [Disclaimers](#)

Developed and maintained by Big Blue Communications for Blue Gold Program



[Blue Gold Program Wiki](#)