

Toggle menu  
Blue Gold Program Wiki

## Navigation

- [Main page](#)
- [Recent changes](#)
- [Random page](#)
- [Help about MediaWiki](#)

## Tools

- [What links here](#)
- [Related changes](#)
- [Special pages](#)
- [Permanent link](#)
- [Page information](#)

## Personal tools

- [Log in](#)

## personal-extra

Toggle search

Search

Random page

## Views

- [View](#)
- [View source](#)
- [History](#)
- [PDF Export](#)

## Actions


# File:P29 IWM Final Report polder29 red 24may 16.pdf

From Blue Gold Program Wiki

The printable version is no longer supported and may have rendering errors. Please update your browser bookmarks and please use the default browser print function instead.

- [File](#)
- [File history](#)

- [File usage](#)



Go to page



[next page →](#)

Size of this JPG preview of this PDF file: [423 × 599 pixels](#). Other resolution: [169 × 240 pixels](#).

[Original file](#) (1,239 × 1,754 pixels, file size: 4.02 MB, MIME type: application/pdf, 118 pages)


Study of riverbank erosion (revised edition incorporating EM comments)

P29

the removal of materials in the river bank by water flowing in the river channel; also termed bank scour. In coastal polders, riverbank erosion - if unchecked - can result in breaches to polder embankments - where they are aligned close to rivers - and consequent loss of human and animal life as well as damage to farmland, crops, housing, and other infrastructure.

## File history

Click on a date/time to view the file as it appeared at that time.

Date/Time	Thumbnail	Dimensions	User	Comment
current <a href="#">19:26, 8 July 2020</a>		1,239 × 1,754, 118 pages (4.02 MB)	<a href="#">Saad.chowdhury</a> ( <a href="#">talk</a>   <a href="#">contribs</a> )	

You cannot overwrite this file.

## File usage

There are no pages that use this file.

Retrieved from

"[https://www.bluegoldwiki.com/index.php?title=File:P29\\_IWM\\_Final\\_Report\\_polder29\\_red\\_24may\\_16.pdf&oldid=2967](https://www.bluegoldwiki.com/index.php?title=File:P29_IWM_Final_Report_polder29_red_24may_16.pdf&oldid=2967)"

## Namespaces

- [File](#)
- [Discussion](#)

## Variants

[Categories](#):

- [P29](#)
- [IWM](#)
- [Report](#)
- [Documents in English](#)
- [Study](#)
- [Erosion](#)
- [BGIF](#)

This page was last edited on 8 July 2020, at 19:29.

## Blue Gold Program Wiki

The wiki version of the Lessons Learnt Report of the Blue Gold program, documents the experiences of a technical assistance (TA) team working in a development project implemented by the Bangladesh Water Development Board (BWDB) and the Department of Agricultural Extension (DAE) over an eight+ year period from March 2013 to December 2021. The wiki lessons learnt report (LLR) is intended to complement the BWDB and DAE project completion reports (PCRs), with the

aim of recording lessons learnt for use in the design and implementation of future interventions in the coastal zone.

- [Privacy policy](#)
- [About Blue Gold Program Wiki](#)
- [Disclaimers](#)

Developed and maintained by Big Blue Communications for Blue Gold Program



[Blue Gold Program Wiki](#)