

☐ Toggle menu
Blue Gold Program Wiki

Navigation

- [Main page](#)
- [Recent changes](#)
- [Random page](#)
- [Help about MediaWiki](#)

Tools

- [What links here](#)
- [Related changes](#)
- [Special pages](#)
- [Permanent link](#)
- [Page information](#)

Personal tools

- [Log in](#)

personal-extra

☐ Toggle search

Search

Random page

Views

- [View](#)
- [View source](#)
- [History](#)
- [PDF Export](#)

Actions

File:Figure 11.2.jpg

From Blue Gold Program Wiki

The printable version is no longer supported and may have rendering errors. Please update your browser bookmarks and please use the default browser print function instead.

- [File](#)
- [File history](#)
- [File usage](#)



Size of this preview: [800 × 450 pixels](#). Other resolutions: [320 × 180 pixels](#) | [1,379 × 776 pixels](#).

[Original file](#) (1,379 × 776 pixels, file size: 232 KB, MIME type: image/jpeg)

The third breach in the realigned embankment (August 2015)

Earthen dyke or bundh raised above surrounding ground level, for example so that roads or railway lines are above highest flood levels, or so that an area is empoldered to protect it from external floods and saline waters.

File history

Click on a date/time to view the file as it appeared at that time.

	Date/Time	Thumbnail	Dimensions	User	Comment
current	07:00, 9 May 2021		1,379 × 776 (232 KB)	Bigblue (talk contribs)	

You cannot overwrite this file.

File usage

The following page uses this file:

- [11 Investments for Polder Safety and Water Management](#)

Retrieved from "https://www.bluegoldwiki.com/index.php?title=File:Figure_11.2.jpg&oldid=5358"

Namespaces

- [File](#)
- [Discussion](#)

Variants

This page was last edited on 9 May 2021, at 07:00.

Blue Gold Program Wiki

The wiki version of the Lessons Learnt Report of the Blue Gold program, documents the experiences of a technical assistance (TA) team working in a development project implemented by the Bangladesh Water Development Board (BWDB) and the Department of Agricultural Extension (DAE) over an eight+ year period from March 2013 to December 2021. The wiki lessons learnt report (LLR) is intended to complement the BWDB and DAE project completion reports (PCRs), with the aim of recording lessons learnt for use in the design and implementation of future interventions in the coastal zone.

- [Privacy policy](#)
- [About Blue Gold Program Wiki](#)
- [Disclaimers](#)

Developed and maintained by Big Blue Communications for Blue Gold Program



[Blue Gold Program Wiki](#)